
BEQ Interior Wall Finish Option





Typical BEQ corridor... exposed unfinished new CMU





Corridor after the use of SKIMM_® to float the block (not cured) – block lines gone





Corridor almost complete... SKIMM & Plexture[®] have been applied to the walls...sleeping quarters finished the same



